

# Acoustical Ceiling Products

## Material Safety Data Sheet

### TRADE NAMES: Celotex® Brand

(Nodular – Safetone® Class A and Protectone®)

**Cashmere®, Cashmere Custom Options, Cashmere Designer Series, Cashmere Frameworks, Cashmere High NRC, Cashmere Integrated Accents, Cashmere Imagination, Cashmere Invisigrille™, Cashmere Style Edge**

MSDS #: 0005-89H

Effective Date: 6/17/02

Revised Date: 3/18/04

### Interior Pro™ Brand

(Nodular – Class A and Time-Rated)

**Sky™**

BPB America Inc.

5301 West Cypress St., Suite 300

Tampa, FL 33607-1766

Phone: 813-286-3900

Contacts: BPB Customer Response Center 1-866-427-2872

www.bpb-na.com

## I. PRODUCT IDENTIFICATION

**Products:** Nodular (Safetone Class A, Protectone and Time-Rated) Acoustical Ceiling Products.

## II. INGREDIENTS

Material	CAS Number	WT%* (Approx.)	OSHA PEL**	ACGIH TLV***	Comments
01 Slag Wool	NONE	<92	5	10	mg/m <sup>3</sup> Resp
02 Starch	9005-84-9	<11	5	10	mg/m <sup>3</sup> Resp
03 Cellulose	9004-34-6	<20	5	5	mg/m <sup>3</sup> Resp
04 Perlite	93763-70-3	<37	5	10	mg/m <sup>3</sup> Resp
05 Clay	1332-58-7	<16	5	10	mg/m <sup>3</sup> Resp
06 Crystalline Silica	14808-60-7	<5	0.1	0.1	mg/m <sup>3</sup> Resp

\* % Approximate

\*\*PEL - OSHA Permissible Exposure Limit, 1910.1000, Nuisance Dust (Respirable)

\*\*\*TLV - Threshold Limit Value, adopted by American Conference of Governmental Industrial Hygienists, 1984-85

OSHA/PEL = 10 / (2X% SiO<sub>2</sub>) mg/m<sup>3</sup> Respirable

OSHA/PEL = 10 / (2X% SiO<sub>2</sub>) MG/M<sup>3</sup> Respirable

ACGIH/TLV = 1 Fiber/CC Respirable

NA = Not Applicable, NE = Not Established

Carcinogenicity

NTP Listed

IARC Listed

OSHA Regulated

**Ingredient Number:**

06



---

**SARA Title III Section 313:**

**Ingredients Listed:** All ingredients of this product are included in the U.S. Environmental Protection Agency's Toxic Substances Control Act (TSCA) Chemical Substance Inventory and the Canadian Domestic Substances List (DSL) or the Canadian Non-Domestic Substances List (NDSL).

As a manufactured article this product is exempt from the requirements of Canada's WHMIS.

### III. PHYSICAL DATA

<b>Boiling Point:</b>	N/A	<b>Sp. Gravity:</b>	SAFE .16 - .25
<b>Vap Pressure:</b>	N/A		PROT. .30 - .40
<b>Vap Density:</b>	N/A	<b>PCT. Volatiles:</b>	N/A
<b>Sol. in Water:</b>	N/A	<b>EVAP. Rate:</b>	N/A
		<b>Appearance/Odor:</b>	Various Colors: Earthy odor.

### IV. FIRE AND EXPLOSION HAZARD DATA

<b>Flash Point (method):</b>	N/A
<b>Flammable Limits:</b>	LEL % N/A UEL % N/A
<b>Extinguishing Media:</b>	Water fog, foam or dry chemical.
<b>Sp. Fire Fighting Procedures:</b>	None Known
<b>Unusual Fire &amp; Explosion Hazards:</b>	May smolder - extinguish completely.
<b>NFPA Ratings:</b>	4 = Severe Hazard, 3 = Serious Hazard, 2 = Moderate Hazard, 1 = Slight Hazard, 0 = Minimal Hazard
<b>Flammability:</b>	0
<b>Health:</b>	0
<b>Reactivity:</b>	0
<b>Special Hazards:</b>	

### V. HEALTH HAZARD DATA

**Primary Routes of Exposure:**

INHALATION:	1. Dust generated from making modifications of tile may cause temporary irritation. 2. Prolonged exposures to high levels of respirable dust may cause a loss or reduction of pulmonary functions.
SKIN:	Contact with dust generated from making modifications of tile may cause irritation.
INGESTION:	N/A
EYE:	Dust generated from making modifications of tile may cause irritation.

**Signs & Symptoms of Overexposure:**

Acute	Irritation of eyes, nose, throat, lungs and or skin.
Chronic	Loss or reduction of pulmonary functions. In October 2001, the International Agency for Research on Cancer (IARC) concluded there is "no evidence" for the carcinogenicity of man-made vitreous fibers (glass wool, rock wool and slag wool) in humans. Epidemiologic studies published during the 15 years since the previous IARC Monographs review of these fibers in 1988 provide no evidence of increased risks of lung



cancer or of mesothelioma from occupational exposures during manufacture of these materials, and inadequate evidence overall of any cancer risk. IARC states that man-made vitreous fibers (glass wool, rock wool and slag wool) are "not classifiable as to carcinogenicity to humans" (Group 3).

In June 1997, the International Agency for Research on Cancer (IARC) concluded there is "sufficient evidence" in humans for the carcinogenicity of inhaled crystalline silica in the form of quartz or cristobalite from occupational sources. In making the overall evaluation, the Working Group noted that carcinogenicity in humans was not detected in all industrial circumstances studied. Carcinogenicity may be dependent on inherent characteristics of the crystalline silica or on external factors affecting its biological activity or distribution of its polymorphs. IARC states that crystalline silica inhaled in the form of quartz or cristobalite from occupational sources "is carcinogenic to humans" (Group 1).

Respiratory illness.

**Aggravated Medical Conditions:**

**Emergency and First Aid Procedures:**

Inhalation  
Eyes  
Skin  
Ingestion

Remove to fresh air.  
Flush with fresh water.  
Wash with mild soap and water.  
N/A

**Other:**

## VI. REACTIVITY DATA

**Stable**

**Conditions to avoid:**

High humidity and water.

**Incompatibilities:**

Strong acids.

**Hazardous Decomposition Products:**

H<sub>2</sub>S gas can be formed on contact with strong acids.

## VII. SPILL OR LEAK PROCEDURES

**Steps to be taken in case**

**material is released or spilled:**

Broken or damaged tiles should be picked up and placed in a container. Dust generated from making modifications of tile should be cleaned by wet wiping or filtered vacuuming. Do not dry sweep or use compressed air to remove dust.

**Disposal Method:**

Dispose in accordance with Federal, State and Local regulations.

## VIII. SPECIAL PROTECTION INFORMATION

**Ventilation:**

Exhaust ventilation.

**Respiratory Protection  
(use only NIOSH/MSHA  
certified devices):**

Wear respirator if airborne concentrations are at or above the PEL.

**Protective Clothing:**

Wear long sleeved, loose fitting shirts or blouses that are closed at the neck and wrist if airborne concentrations are at or above the PEL. Gloves, long pants, and caps should also be considered.

**Eye Protection:**

Wear safety glasses or goggles.



---

## IX. SPECIAL PRECAUTIONS

### **WARNING:**

This product contains crystalline silica. Minimize dust during cutting and trimming of these products. Avoid breathing dust/fiber and placing these materials in contact with skin or eyes to avoid irritation. When making modifications of tile, do not cut with power equipment, unless the equipment utilizes a dust collection system which maintains the exposure level below the OSHA/PEL. Use a NIOSH/MSHA approved dust mask when dust levels exceed the OSHA/PEL or for comfort. Failure to follow these instructions may result in over exposure to airborne respirable crystalline silica dust which can cause eye, skin, respiratory irritation and in some cases loss of pulmonary functions. Studies have found that breathing respirable airborne crystalline silica dust can also cause silicosis. Sustained high level exposure increases these risks. Smoking greatly increases health risks, including the risk of cancer and other diseases.

### **RECOMMENDED WORK PRACTICES:**

#### **PREVENT DUST:**

When making modifications of tile, do not use power equipment. Use local exhaust ventilation whenever the dust exposure may exceed established allowable levels. Operations which have the potential to create high dust exposure, such as power cutting, power kerfing or use of compressed air to remove (blow down) dust must be avoided.

#### **USE RESPIRATORS:**

In work settings, where dust levels are at or above allowable levels use a NIOSH/MSHA approved respirator. Consult respirator manufacturers for specific recommendations on the proper respirator. An appropriate fit testing program must be incorporated in all respiratory protection programs.

#### **PROTECT YOUR EYES:**

Wear safety glasses or goggles whenever handling or installing ceiling tile.

#### **WEAR PROPER CLOTHING:**

Wear long sleeved, loose fitting shirts or blouses that are closed at the neck and wrists, along with long pants and caps, to help prevent the skin from coming into contact with ceiling tile dust. Depending upon job conditions, gloves may also be necessary.

#### **PROTECT YOUR SKIN:**

If ceiling tile dust gets on your skin, do not rub or scratch that area. Remove the dust by washing your skin thoroughly, but gently, with warm water and mild soap. Using a skin cream or lotion after washing may also help.

#### **KEEP YOUR WORK AREA CLEAN:**

Avoid unnecessary handling of scrap ceiling tile material or debris pile up on the floor. Follow an organized house keeping program at all times.

#### **CLEAN UP PROCEDURES:**

Surfaces where dust collects must be cleaned by wet wiping or filtered vacuuming. Do not dry sweep or use compressed air to remove dust.

---

As of the date of preparation of this document, the foregoing information is believed to be accurate and is provided in good faith to comply with applicable Federal and State Laws. However, no warranty or representation with respect to such information is intended or given.

